

Settling Time of Model 84053 Ceramic Sensors

Tech Note

84053 Ceramic Sensor Settling Tests

Sensor installed in Model 801-H/L Tuff Tilt (SN2126) mounted to 3-legged plate set on granite flat
Test #3 12-21-05 14:55-15:21 Vigorous shake, off slab, upside down +/- Tilt

